

AMENDMENTS TO SENATE BILL NO. 453

Sponsor: SENATOR J. WARD

Printer's No. 448

1 Amend Bill, page 2, line 14, by inserting after "building"
2 at the owner's expense

3 Amend Bill, page 2, lines 16 and 17, by striking out
4 "construction code official" and inserting
5 code administrator

6 Amend Bill, page 2, line 24, by striking out all of said line
7 and inserting

8 (ii) The building has functioning:

9 (A) hard-wired smoke detectors if electrical
10 wiring has been installed in the interior of the
11 building; or

12 (B) battery-powered detectors if electrical
13 wiring has not been installed in the interior of the
14 building.

15 Amend Bill, page 2, line 29, by striking out "construction
16 code official" and inserting
17 code administrator

18 Amend Bill, page 3, line 13, by striking out all of said line
19 and inserting

20 and similar social events that state:

21 (A) The maximum occupancy of the building per
22 the requirements of the International Building Code
23 that was part of the Uniform Construction Code at the
24 time of the inspection.

25 (B) "This facility is

26 Amend Bill, page 3, by inserting between lines 16 and 17

27 (ix) Unless permitted toilet facilities are provided
28 on the grounds of the building, portable toilet
29 facilities are provided in accordance with the minimum
30 number of required toilets for a restaurant or banquet

1 hall in the International Building Code that was part of
2 the Uniform Construction Code at the time of inspection.

3 (x) An inspection report by a code administrator
4 states that the building complies with the accessibility
5 provisions for historic buildings in the International
6 Code Council's International Existing Building Code
7 determined by the Accessibility Advisory Board.

8 (xi) An inspection report by a code administrator
9 states that the building complies with the change of use
10 provisions for historic buildings in the International
11 Code Council's International Existing Building Code that
12 was part of the Uniform Construction Code at the time of
13 inspection.

14 (xii) The primary function remains on the level of
15 exit discharge. The occupancy level of the stories in a
16 multilevel building must be determined by the code
17 administrator and may not to exceed levels as determined
18 by the International Building Code that was part of the
19 Uniform Construction Code at the time of inspection.