
Abandoned Oil and Gas Wells

B SRI Streets 8 Imagery | Topographic | National Geographic | PA Map Imagery (2003-2004) 8 ESRI Imagery |


| Value | V

Abandoned Conventional Wells



Abandoned Unconventional Wells
(Is history repeating itself?)

Abandoned Injection Wells



Abandoned well: Well that has not been operated in 12 months (and not granted inactive status).

Orphan well: well that has no identifiable operator.

DEP inspection report photo abandoned unconventional well



In 1992, the legislature amended the Oil and Gas Act of 1984 allowing oil and gas wells that were abandoned before April 18, 1979 to be classified as **orphan wells**.

This re-classification transferred the responsibility to plug tens of thousands of wells onto Pennsylvania, if landowners, leaseholders and oil and gas operators received no economic benefit from the wells after April 18, 1979.

Reclassifying abandoned wells into orphan wells did not include a sufficient revenue source for plugging these newly classified orphan wells, ensuring that generations of Pennsylvanians going forward would bear the responsibility for their plugging, monitoring and re-plugging.



Photo: by Barbara Laxon A leaking plugged well in McKean County 03/21/2024

How many abandoned wells are there?



 Experts estimate there may be 382,000 - 750,000 abandoned oil and gas wells in PA.

(Estimates: Engelder 382K, Kang 750K)


- The vast majority of these were drilled prior to well permitting requirements and remain unaccounted for.
- At the current rate of plugging ~200 wells per year it would take Pennsylvania 1,910 – 3,750 years to initially plug 382K-750K wells.
- The current cost of plugging well has been ~\$100,000 per well (through IIJA contracts).
- Before the IIJA funding there was limited funding to plug orphan and abandoned wells in Pennsylvania.
- At \$100K per plug it would cost
 \$38,200,000,000,00 \$75,000,000,000.00
 to plug Pennsylvania's estimated 382K-750K wells.

Photo: Natural gas and fluid pouring from an abandoned well into a stream in Potter County, PA

Welcome! Organization Production Data Permitting Inspections and Compliance Active Wells <u>Pennsylvania's</u>
pollution and/or pose public safety risks if not properly plugged.

To date, the Department has documented approximately 27,000 orphan and abandoned wells located on state or private land. The estimated cost to plug these wells is about \$1.8 billion. Before 2022, there has been limited state funding to plug and remediate orphan and abandoned oil and gas wells in Pennsylvania. The Pennsylvania Oil and Gas Act created two special funds called the Abandoned Well Plugging Fund and the Orphan Well Plugging Fund. The Orphan and Abandoned Well Plugging Funds receive revenue from a nominal permit surcharge authorized by the 2012 Oil and Gas Act (\$150 per oil well permit and \$250 per gas well permit). 58 Pa.C.S. § 3271. These permit surcharges are grossly insufficient to cover the cost of properly plugging all orphan and abandoned wells that currently exist in Pennsylvania and they have been used primarily to pay for plugging orphan and abandoned wells in emergency situations where potential human health or environmental contamination is of concern.

- DEP has documented approx 27,000 orphan and abandoned wells.
- Plugging 27,000 wells @ \$100,000 = 2.7 Billion
- It would take 135 years for the DEP to plug 27,000 wells at 200 wells per year.



How long do cement plugs last?

- Oriskany well drilled in 1936
- Initially plugged in 1972
- Re-plugged in 1994
- Re-plugged again in 2012

I asked the operator about the cost of re-plugging. He explained re-plugging cost around "one million".

The reason for the high cost he explained is because the previous plug had to be drilled out/removed.

Photo by Laurie Barr Re-plugging operation within the boundary of an underground gas storage field, Sabinsville, PA. 2012

Less than one year old plug failed.

Initially plugged in 2014, re-plugged (successfully), along with 6 other wells through a DEP plugging contract in 2016. Otto Twp., McKean County, PA.



Video of failed well plug here: https://www.cardcreek.com/Other/Video-link-to-share/i-rxBgB6L/A





Unplugged wells may and often do act as pathways for gases or liquids to migrate from deep formations into the aquifer or to the surface. Their wooden, steel & cement casings deteriorate over time creating pathways that allow fluids and gases to migrate.

2009

Department of Environmental Protection report titled Stray gas migration associated with Oil and Gas Wells lists dozens of incidents of stray gas migration, many of these were associated with abandoned oil and gas wells. https://docs.google.com/document/d/1F111iK5bgws9Wbbe2svvc1bp6WripHzpgXv_pvLCxRl/edit?usp=sharing

2010 & 2011

2 homes exploded in the Historic Bradford Oil Field in (McKean County) in 2010 & 2011 due to methane migration.

After the 2nd home exploded the DEP ordered a nearby operator to plug three nearby abandoned wells that were discovered during the investigation.






After the two homes exploded in 2010 & 2011, Senator Bob Casey wrote to the Department of Energy Secretary Steven Chu;

"I am deeply alarmed to learn of yet another gas-migration-related explosion in Pennsylvania," his letter urged the secretary to "coordinate with local, state, and other federal entities to ensure that appropriate actions to protect public health are implemented."

http://www.casey.senate.gov/newsroom/press/release/?id=c7091fea-fc47-42bc-90ea-d35e886e53df



2019

Bradford Oil Field, Allegany, NY A third home in the area exploded. This was approx 11.3 miles from where the home that exploded in 2010 was located.

The Bradford Oil Field extends from PA Into New York State.

This home was located in Allegany, NY in the Bradford Oil Field. The Bradford Oil Field extends over the PA border into New York State.



Not all abandoned wells are shallow wells


HISTORY OF DEEP-SAND EXPLORATION Attempts to discover oil and gas in the more deeply buried formaunder western Pennsylvania, that is those below the relatively shaland extensively drilled Upper Devonian sands, have been made from time time since the late 80's. The well of the Presque Isle Natural Gas Comdrilled to a depth of 4,460 feet between October 1887 and January 1889 the City of Erie, was one of the earliest of these. The well penetrated the Trenton limestone to a depth of 210 feet and remained the only well to this formation in western Pennsylvania until 1941. The R. A. Geary well of the Peoples Natural Gas Company, 5 miles northwest of McDonald in wington County, was drilled in 1917 to a depth of 7,248 feet into strata of Salina age. At that time it was the deepest well in the United States and second deepest in the world. In 1925 the same company's Booth and Flinn No. 2 well at McCance, Westmoreland County, also bottomed in the Salina formation at a depth of 7,756 feet, had the distinction of being the deepest well in the world. By 1930 at least 36 wells had been drilled to the Ononor deeper.

Year(s) drilled	Depth
1887 - 1889	4,460'
1917	7,248'
1925	7,756'

Summarized record of deep wells in Pennsylvania / by Chas. R. Fettke


by Fettke, Charles R . 1950: https://archive.org/details/summarizedrecord00fett/page/n19/mode/2up

Some old abandoned conventional wells are deeper than newer abandoned unconventional wells



DEP's Oil and Gas Well Map

Potter County



The grey circles are well locations identified by the topographic (base) map. DEP only has records on the well locations Identified by the (colorful) icons listed on the legend on the left of the map.

https://www.depgis.state.pa.us/PaOilAndGasMapping/OilGasWellsStrayGasMap.html

Washington County

This is the location of an oil well identified on a topo map. Similar to the previous slide, wells are identified on this map as small circles. Some are also labeled with the words "oil well." Location: 40.446647, -80.159913




https://www.arcgis.com/apps/mapviewer/index.html?layers=99cd5fbd98934028802b4f797c4b1732


Washington County, Kohl's Department and Clothing Store

This is the location of a well identified on a topo map. The recorded well location (on the TOPO map) is identified by the red icon on the Google map below.

Location on Google Map: 40.446647, -80.159913, Kohl's Department & Clothing Store



https://www.google.com/maps/



Kohl's Department and Clothing Store Location: 40.446647, -80.159913

_


Safety issues arise, especially when unknown abandoned wells are located within close proximity to construction, excavation, drilling and fracking, under or near homes and other structures.

Location: 40.443034, -80.154560




The locations of the O&G wells on the TOPO map may not be accurate. https://www.arcgis.com/apps/mapviewer/index.html?layers=99cd5fbd98934028802b4f797c4b1732

The Bradley Center is located at the well location, identified by the TOPO map from the previous slide.



https://www.google.com/maps/place/5180+Campbells+Run+Rd,+Pittsburgh,+PA+15205/@40.4429184,-80.1570394,17z/data=!3m1!4b1!4m6!3m5!1s0x8834593b51a81c6f:0x59a7c2ebae17a6c2!8m2!3d40.4429184!4d-80.1544591!16s%2Fg%2F11bw4jnsz_?authuser=0&entry=ttu

The Bradley Center at the location of a well identified by DEP's oil and gas well map.



Source: https://gis.dep.pa.gov/PaOilAndGasMapping/OilGasWellsStrayGasMap.html

Location: 40.443034, -80.154560



Contact Us | Blog



4000' communication between wells




1990's in McKean County: The PADEP responded to a complaint of gas escaping from an abandoned gas well located in a wooded area near the Foote Rest CampGround.

During the investigation, it was discovered that an extremely large amount of (estimated at more than 100 Mcf/day) was venting from the abandoned gas well.

The old well became activated when fracking was completed on a new gas well approximately 4000'away.

DEP Oil and Gas Map showing a 4000' buffer around the newly permitted Cyclone injection well



The icons identify the locations of wells DEP has records on.

The Department of Conservation and Natural Resources (DCNR), Geological Survey manages the Exploration and Development Well Information Network (EDWIN) an oil and gas well database. EDWIN provides oil and gas well operators, landowners or those planning, coordination and control of a construction projects with valuable information on the locations of abandoned wells.

EDWIN subscribers may access the data for a **\$5,500.00** fee or by visiting the DCNR office in Pittsburgh. However the DCNR work stations desperately need upgrade.

EDWIN records completion reports, depth of wells and also location information on some wells that are not available through any other database.



Home Subscribe FAQ Contact Log in



EDWIN Subscriptions

Those desiring the convenience of 24/7 remote access to Pennsylvania's oil and gas well information may subscribe to EDWIN. The subscription includes the software license for accessing the system, technical training and support on the use of the system, and as-needed software upgrades and maintenance. The initial subscription fee is \$5,000, which covers the software license and initial training on use of the system. An annual maintenance fee of \$500 covers technical support and troubleshooting, geologic consultations, and software upgrades and maintenance during the subscription year.

Subscribe

Ready to subscribe to EDWIN? Click below to create your account and establish your subscription!

Subscribe

Contact Us

Have questions about EDWIN? Need help with your existing account? Click below to get in touch with us!

Contact Us


Pennsylvania has the potential to receive over 300 million to plug abandoned oil and gas wells over the next 10 years through the Infrastructure Investment and Jobs Act (IIJA).







DEP created a list of wells to be plugged with IIJA funding and that list is available on the DEP's Infrastructure Investment and Jobs Act (IIJA) page.



<u>Link: https://www.dep.pa.gov/Business/Energy/OilandGasPrograms/OilandGasMgmt/LegacyWells/Pages/Infrastructure-Investment-and-Jobs-Act-(IIJA).aspx</u>

Human Receptors Choose Up To 5	
Gas in occupied structure with similar isotopic signature or believed to be associated with well*	50 -
Oil/brine in occupied structure believed to be associated with well*	50 -
Soil gas within 200 feet of structure believed to be associated with well	25 -
Gas in water supply	25 -
Oil/brine in water supply	15 -
	_ (_ o
Ecological Receptors Choose Up to 2	
Liquids (ail/brine) to stream or wetland from well	25 -
Oi/brine seep (discharge not from wellbore)	10 -
Olidina saap (discharge not nom wadore)	10
	1 0
Well Site Hazards Choose Up to 4	
Any ambient H ₂ S detection	25 -
Any ambient LEL readings ≥ 10%	25 -
Sustained ambient LEL <10%	10 -
Unstable equipment, open pits, E&S issues/washouts	10 -
Evidence of historical liquid spills not associated with well integrity breach	5 -
	(o
Well Integrity Chaose Up to 4	
Gas present outside surface casing/present in stream or liquid flow to surface	25 -
Measurable annular flow of gas	15 -
Welhead pressure observed	10 -
Severe corrosion (pitting) on well component that possibly contains pressure or fluids	10 -
Control Control of Party of Wall Composition in the position of Control of Trade	10
Coal/Mining Status Choose Up 76 1	
Well within active underground mine (sealed or undergoing mining .i.e., longwall district)	25 -
Within abandoned mined area	
	25 -
Permitted but not yet mined (intact coal/rock) ¹	10 -
Workable coal present but not permitted	5 -
	0
Setback/ Surrounding Area Choose Up to 4	
Setback/Surrounding Area Choose Up to 4 Well within 200 feet of occupied building or water supply well	10 -
	10 - 5 -
Well within 200 feet of occupied building or water supply well	5 -
Well within 200 feet of occupied building or water supply well Well located in known gas migration area but not believed to be source Well within 100 feet of stream	
Well within 200 feet of occupied building or water supply well Well located in known gas migration area but not believed to be source	5 -
Well within 200 feet of occupied building or water supply well Well located in known gas migration area but not believed to be source Well within 100 feet of stream	5 -

- Abandoned and Orphan wells are prioritized for plugging based on the DEP's <u>internal</u> <u>scoring system</u>.
- DEP considers a well that scores greater than 75 to be a priority for plugging due to their elevated threats to human health, wildlife, and the environment.

 $\frac{https://files.dep.state.pa.us/OilGas/BOGM/BOGMPortalFiles/AbandonedOrphanWells/IIJA/Internal%20Sheet_Scoring%20System.xlsx$

A1	▼ f.	Wells in RED are highest scoring priority v	ells; all oth	ner wells are in pro	ximity to priority wells for prefer	ed contract gro	ouping.				
	А	В	С	D	Е	F	G	Н	I		
1	Wells in RED are highest scoring priority wells; all other wells are in proximity to priority wells for preferred contract grouping.										
2	API ₹	FARM NAME	WELL∣∓	COUNTY =	MUNICIPALITY =	LAT DECIN =	LON DECIM =	WELL STATUS ₹	TOTAL POIN =		
3	003-22594	Camp Horne Road	1	Allegheny	Emsworth Borough	40.51396	-80.09166	DEP Abandoned	115		
4	003-01113	Liggett	2	Allegheny	Forward Twp.	40.20064	-79.916346	DEP Abandoned	8		
5	003-01105	Forgie	1	Allegheny	White Oak Borough	40.342433	-79.814121	DEP Abandoned	78		
6	003-22244	Hartman	1	Allegheny	White Oak Borough	40.349344	-79.813245	DEP Abandoned	77		
7	003-22595	Roosevelt Road	1	Allegheny	Ohio Township	40.54823	-80.10204	DEP Abandoned	55		
8	003-01098	Graham	1	Allegheny	Sewickley Heights Borough	40.518472	-80.194008	DEP Orphan	25		
9	003-01259	Brightwood	1	Allegheny	Kennedy Twp.	40.494139	-80.108139	DEP Abandoned	58		
10	003-22596	Barensfeld	1	Allegheny	Sewickley Heights Boro	40.58155	-80.14774	DEP Abandoned	30		
11	003-01196	Jacks Run	1	Allegheny	Ross Twp.	40.49975	-80.04555	DEP Abandoned	34		
12	003-01197	Jacks Run	2	Allegheny	Ross Twp.	40.499133	-80.047983	DEP Abandoned	29		
13	003-01198	Jacks Run	3	Allegheny	Ross Twp.	40.500083	-80.047067	DEP Abandoned	15		
14	003-01260	Richard Street	1	Allegheny	Kennedy Twp.	40.494222	-80.106028	DEP Abandoned	59		
15	003-01267	Shannopin Country Club	1	Allegheny	Kilbuck Twp.	40.514	-80.066389	DEP Abandoned	39		
16	003-01106	Liggett	1	Allegheny	Forward Twp.	40.200097	-79.914928	DEP Orphan	25		
17	003-01208	Evans	1	Allegheny	Forward Twp.	40.230219	-79.87695	DEP Abandoned	39		
18	003-01216	4307 3rd St.	1	Allegheny	Versailles Borough	40.321256	-79.837281	DEP Abandoned	69		
19	003-01240	Saraka	1	Allegheny	Versailles Borough	40.315972	-79.8345	DEP Abandoned	25		
20	003-01245	OH Well	1	Allegheny	Versailles Borough	40.315825	-79.834897	DEP Abandoned	64		
21	003-01086	Nock	1	Allegheny	Ohio Twp.	40.534392	-80.210853	DEP Orphan	31		
22	002 01217	Davolanare Diversified	1	Alloghopy	Ohio Turo	AN E221E0	00 050204	DED Abandonod	10		

DEP's priority well list includes :

- Many wells DEP could not locate (and scored anyway).
- Wells EPA plugged in 2016 through a contract with Cline Oil.
- Wells that are in use.

Casing	Size	Press (psi)	Volur	ne (cu ft/d)	Length (ft)	SIPT	Additional Comments
Cellar Observation					Equipment on L	ocation	
Water ☐ Yes ☐ No		Below Grade:	Below Grade: ft				Meters:
Gravel Yes No		Below Grade:	ft		Pumpjacks:		Tanks:
Bubbling Yes No		Rate:			Separators:		
Combustible Gas Detected		Date Calibrated:			Drips:		Containment:
Yes No unchecked							
Gas Concentration		Method Used:			Wellhead Obse	rvations	
% LEL % Gas					0 1		
H2S Detected Yes No			ppn	n	Corrosion:		Leaking:
	Documents V	VQS follow up					
✓ Yes No		Yes 🗹 No		Inspection Results	NOVIO - No	o Violations	Noted
Remarks: Inspected well site per Harris	burg request to up	date current plugging	g list. V	Was unable to find well	anywhere on sh	oreline near	location of record (well plot is IN
the Momongahela River). Did find a circ	cular concrete pad	along shore (photos)	of un	nknown purpose.			
On Site Representative				DEP Representative			
(signature)			(signature)				
1-8				MARK BARNES - OIL AND GAS INSPECTOR			
(print name)			(print name)				
Date: 02-12-2020	Time Arrived	: 12:40 PM		Tir	ne Departed: 01:	35 PM	


The inspector was "unable to find" priority well #2

It was highlighted in red and given a score of 83 anyway.

WERS IN NEW DIE HIGHEST STOTHIG PROTECT WERS, ON OTHER WERS DIE IN PROXIMITY TO PROTECT WERS FOR PREFERENCE CONTRACT GROUPING.

2	API ₹	FARM NAME =	WELL।₹	COUNTY =	MUNICIPALITY =	LAT DECIN ₹	LON DECIM =	WELL STATUS ₹	TOTAL POIN ₹	
3	003-22594	Camp Horne Road	1	Allegheny	Emsworth Borough	40.51396	-80.09166	DEP Abandoned	115	
4	003-01113	Liggett	2	Allegheny	Forward Twp.	40.20064	-79.916346	DEP Abandoned	83	4
5	003-01105	Forgie	1	Allegheny	White Oak Borough	40.342433	-79.814121	DEP Abandoned	78	
6	003-22244	Hartman	1	Allegheny	White Oak Borough	40.349344	-79.813245	DEP Abandoned	77	
7	003-22595	Roosevelt Road	1	Allegheny	Ohio Township	40.54823	-80.10204	DEP Abandoned	55	
8	003-01098	Graham	1	Allegheny	Sewickley Heights Borough	40.518472	-80.194008	DEP Orphan	25	
9	003-01259	Brightwood	1	Allegheny	Kennedy Twp.	40.494139	-80.108139	DEP Abandoned	58	
10	003-22596	Barensfeld	1	Allegheny	Sewickley Heights Boro	40.58155	-80.14774	DEP Abandoned	30	
11	003-01196	Jacks Run	1	Allegheny	Ross Twp.	40.49975	-80.04555	DEP Abandoned	34	
12	003-01197	Jacks Run	2	Alleghenv	Ross Twp.	40.499133	-80.047983	DEP Abandoned	29	

#2 on the list scored 83 points "Was unable to find well..."



The 8th well on the IIJA list was *never inspected* according to the DEP records.

The well was given a score of 25

		<u> </u>			_				
7	003-22595	Roosevelt Road	1	Allegheny	Ohio Township	40.54823	-80.10204	DEP Abandoned	55
8	003-01098	Graham	1	Allegheny	Sewickley Heights Borough	40.518472	-80.194008	DEP Orphan	25
9	003-01259	Brightwood	1	Allegheny	Kennedy Twp.	40.494139	-80.108139	DEP Abandoned	58
10	003-22596	Barensfeld	1	Allegheny	Sewickley Heights Boro	40.58155	-80.14774	DEP Abandoned	30
11	003-01196	Jacks Run	1	Allegheny	Ross Twp.	40.49975	-80.04555	DEP Abandoned	34

Well Info	Conventional	Well Kind &	Vertical Well
Well IIIIO	Conventional	Description	VELLICAL YVELI

GENERAL COMMENTS

On Thursday, 1/6/2022, I conducted an inspection of the Polish Falcons of America Nest 159 Polish Falcon 1 well, permit number 005-02359, as part of the Federal Stimulus Well Plugging project. The well is located in a residential yard off of State Route 66 in Manor township, Armstrong county. There are no issues with stream crossings or wetlands, however, the landowner is producing the well for house gas use, as per inspection id #3211712, and the department has received Adopt a Well request, as per inspection #3243075. Thee are no violations being cited for this inspection

Inspection Results	Files Attached	Photos Attached	Date Inspected
NOVIO - No Violations Noted		~	01/06/2022

			ı -						
41	005-02262	Floy L. Campbell	1	Armstrong	Manor Twp.	40.736275	-79.505414	DEP Orphan	15
42	005-02308	Levi Shott	1	Armstrong	Manor Twp.	40.729825	-79.500361	DEP Abandoned	56
43	005-02359	Polish Falcon	1	Armstrong	Manor Twp.	40.729271	-79.536169	DEP Abandoned	28
44	005-02415	Hansotte Plan	3066	Armstrong	Manor Twp.	40.759139	-79.519083	DEP Abandoned	54
45	005-02458	Dupstadt	1	Armstrong	Bethel Twp.	40.697972	-79.549194	DEP Abandoned	32
							·		

pennsylvania
DEPARTMENT OF ENVIRONMENTAL
PROTECTION

v1.1.0

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

INSPECTION REPORT ROUTINE INSPECTION

DEP USE ONLY

Inspection Record No. 3256087

Complaint Record No.

Enforcement Record No.

Remarks:

Several attempts have been made to locate this well. The area is heavily overgrown and no indication of a well. Old inspection report states that well was never physically found. The area is used as hunting grounds for Rosebud Mining. I spoke to some individuals who use the land and none of them have ever seen a well. They went so far as to take a metal detector out to find any indication of a well site, but have not been able to.

On Site Representative	DEP Representative				
	d 100.				

		I L	-						
46	005-02460	Brad Smail	1	Armstrong	Kittanning Twp.	40.727139	-79.493278	DEP Abandoned	22
47	005-02136	J. Seybert	5	Armstrong	Perry Twp.	41.036453	-79.642764	DEP Orphan	13
48	005-02317	Joseph B. John Farm	1	Armstrong	Perry Twp.	41.022131	-79.613533	DEP Abandoned	5
49	005-02360	Jack L. Jones	CW-5	Armstrong	Perry Twp.	41.022932	-79.649643	DEP Abandoned	15
50	005-02150	McCord	2	Armstrong	Hovey Twp.	41.151514	-79.686039	DEP Orphan	13
51	005-02151	McCord	3	Armstrong	Hovey Twp.	41.150747	-79.685983	DEP Orphan	13
52	005-02152	McCord	4	Armstrong	Hovey Twp.	41.150336	-79.686819	DEP Orphan	13
53	005-02229	Mike C. Zitterberg	1	Armstrong	Kiskiminetas Twp.	40.582097	-79.542206	DEP Orphan	15

"Went so far as to take a metal detector..." scored 15 points for the well DEP never located.

H2S Detected Yes No			ppm	C	orrosion:	Leaking:				
Photos Taken ☐ Yes ☑ No	Additional Documents ☐ Yes ☑ No	WQS follow up ☐ Yes ☑ No	Inspection Results		NOVIO - No Violations No	ted				
will be attached to this inspe	Remarks: This inspection was conducted as part of the stimulus planning project. All observations and further observations are included in the survey 123 inspection and will be attached to this inspection. The home owner reports the well was plugged by the EPA and Cline oil company in he estimates 2016.									
On Site Representative			DEP Representative	:						
(signature)			(signature)	M	H.					
(signature)			SCOTT MOTTER - OIL AND GAS INSPECTOR							
(print name)			(print name)							
Date: 06-17-2021	Time Arriv	red: 10:07 AM		Time Dep	parted: 10:38 AM					

173	073-00006	John & Barbara Reed	3	Lawrence	Wilmington Twp.	41.10359	-80.272133	DEP Orphan	15
174	073-20424	944 Indian Run Rd.	1	Lawrence	Wilmington Twp.	41.120528	-80.259306	DEP Abandoned	21
175	083-56907	Irons	1	McKean	Otto Twp.	41.93725	-78.512806	DEP Abandoned	76
176	083-13647	Hostetter or Foster Farm	1	McKean	Bradford Twp.	41.905928	-78.651817	DEP Abandoned	77
177	083-13651	Chide	1	McKean	Foster Twp.	41.922542	-78.567019	DEP Abandoned	76

in Subsection 6.7, Extra work, page 96, of the 2016 General Conditions, as nerein defined and except as in the contract otherwise specifically provided, the following unit or lump sum prices, to wit:

SCHEDULE OF UNIT PRICES

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT	UNIT PRICE	ESTIMATED AMOUNT
1.	Cleaning Out and Plugging	15	L.S.	\$87,998.00	\$1,319,970.00
2.	Fifteen (15) Abandoned Wells Well Head Excavation (as needed)	15	L.S.	100.00	1,500.00
3.	Equipment Removal (as needed)	15	L.S.	100.00	1,500.00


Total Contract Amount:

\$1,322,970.00

\$1,322,970.00 to plug 15 wells in Otto Twp.

https://drive.google.com/file/d/1F8MjSefDxCFjd7eSKpdqjiDinyU7U0a7/view?usp=sharing

Oil & Gas Infrastructure Investment and Jobs Act (IIJA) Project Tracker map identifies 15 wells (13 on Mr. Schimp's land + 2 other wells) in Otto Twp., McKean County.



5500-FM-OG0049	12/94	C
16591	Summit Oil GAS	DEPAR
OGO#	OPERATOR	ANNU

	ME					
WELL IDENTIFICATION						
PERMIT OR REGISTRATION #	FARM NAME	WELL #	SERIAL #	STOCK TANK OR METER NUMBER		
083-39926	Tracy Farm SummiT	F22	306-2	432445		
40388		23				
40389		24				
35761		52				
36097		52				
		Ĺ				
083-33463	DALLAS		1930	432447		
583-3348S		S 115				
043-2//23		2,				
183-41866		3				
183-07765		3/6				

Bureau of Oil and Gas
Planning and Program Management

SEP 2 5 2015


Received

A production report was filed in 2015 by Summit Oil and Gas for 5 wells that were plugged under the Otto Twp. contract.

Summit Oil & Gas Production Report online here: https://drive.google.com/file/d/1RGyQfpupYja5h3PTWADAFQuRgL9c830d/view?usp=sharing



Dashboard Overview of IIJA-Funded Well Plugging PA DEP Contracts





Workers hired by the DEP spent about two months plugging 13 wells on the land, but Schimp said about half of the work they did was replugging already capped wellbores — the drilled holes used to extract oil or gas.

"They've done a good job, but they've plugged wells that didn't need plugging," said Schimp, a retiree who previously worked in the oil and gas industry.

Schimp's wells were plugged as a result of a huge influx of federal funding from the 2021 Infrastructure Investment and Jobs Act.

The IIJA grants are intended to reduce the methane leakage generated by unplugged abandoned wells. These wells can also be hazardous to nearby residents, who can fall into open holes or be harmed by toxic fluids that seep into groundwater.

The program is slated to dole out more than \$4 billion to well plugging efforts across the country, and Pennsylvania could receive as much as \$400 million over the next decade. The money is supposed to target wells that are unproductive and have owners who either can't be located or can't afford to plug the holes themselves.

The commonwealth got its initial \$25 million IIIΔ grant in Διισιετ 2022

Contact Information



Laurie Barr

Email: <u>lauriebarr59@yahoo.com</u>

Phone: 814-203-9772

www.http//saveourstreamspa.org